

Glazier Test Tool, Scanner and SmartSheets

Work Performed by

Glazing contractor and Low-Voltage contractor

Tools Required

- Glazier Test Tool (GTT), provided by View
- QR / Bar code reader, provided by View
- Laptop or Tablet using SmartSheet, provided by others
- Internet Access (Hotspot available from View, if required)

Procedure

1. Glazing/Low-Voltage: Sync scanner with tablet or laptop, instructions are in the box with the scanner
2. Glazing/Low-Voltage: Make sure tablet or laptop are connected to the Internet, if there is no Internet available, View can provide a Hotspot device
3. View PM: Send correct link for SmartSheet to each glazing/low-voltage contractor:
 - a. Step 1: Receipt of glass
 - b. Step 2: Post fabrication
 - c. Step 3: Post installation
 - d. Step 4: Low-voltage only
4. Glazing/Low-Voltage: Open email from View PM, follow link to SmartSheets, create account (free), after the account is setup, you will have access to the sheet, you are ready to scan and test
5. Scan the QR code or bar code into the Lite ID cell
6. Enter Pass or Fail
7. If Fail, select failure mode from drop-down menu
8. Enter field notes, as needed
9. Enter company name
10. Enter technician name
11. Disregard PM/FSE column
12. Repeat
13. Save work in SmartSheets before shutting down computer / tablet
14. Notify View PM when testing is complete
15. At completion of project, return GTT, scanner and Hotspot to View PM

ZEBRA DS3678-ER PROGRAMMING INSTRUCTIONS

Below are the programming instructions for the Zebra scanner and the Tera scanner for a Windows 10 computer or Apple iPad.

If you have any questions please contact your View Project Manager or send questions to: glaziertraining@view.com or lvebootcamp@view.com



Step 1: Reset to scanner to Factory Defaults

Power ON the Zebra scanner and scan the QR codes to reset the scanner to factory defaults (Note: The Zebra scanner must be fully charged)



RETURN TO FACTORY DEFAULTS

Step 2: Initialize scanner & Bluetooth pairing by platform

Apple platform

For the **Mac**, scan this barcode and connect the scanner via Bluetooth



For **iPad**, scan this barcode and connect via Bluetooth.

NOTE:

- Double-click the trigger on the Zebra scanner to access the virtual keyboard
- Single click the trigger on the Zebra scanner to remove the virtual keyboard



Android platform

For **Android**, install the Scan-To-Connect (STC) Utility and connect via Bluetooth for a phone or tablet

https://play.google.com/store/apps/details?id=com.zebra.scantoconnect&hl=en_US&gl=US



Scan-To-Connect (STC) Utility

Zebra Technologies Productivity

★★★★★ 48

Everyone

Add to Wishlist

Install


Windows 10 platform

Option 1: Windows 10 Platform


- Scan barcode



- Go to Settings ---> Devices ---> Bluetooth & Other Devices



- Select DS3678 from the list and click Connect



- “Connected” will appear once the Scanner is paired

Option 2 - Windows 10 Platform

- Enable Bluetooth from Windows 10
- Download and Install Scan-To-Connect (STC) utility for Windows.
<https://www.zebra.com/us/en/support-downloads/software/utilities/cordless-scantoconnect.html>

Download File>> For installation instructions click here.

- Click the Cordless Scan-To-Connect icon to launch the application



- Scan the pairing barcode to pair cordless DS3678 Bluetooth scanner
- After a successful connection, the DS3678 will show as connected



Step 3: Setup delays and tab functionality to ensure proper barcode reading

Once pairing of the scanner is paired with the device, scan the following QR codes **in sequence**, this will ensure the Lite ID is correctly read into SmartSheets:



**Fast HID Disable
(0)**



Long Delay (40 msec)

NOTE: By scanning the above barcodes, we are expecting the data string/scan to be submitted to the host system as a complete set of data. The way you were scanning prior to this formatting/scanning these barcodes, your data string was being submitted to the host system as if it was being rapidly keystroked.

Additional Codes:



Windows and
Mac



iPad with Delay



All Devices

Technical Support:

Michael Solarczyk
Cal-Sierra Technologies, Inc.
39055 Hastings St. Ste 103 | Fremont, CA 94538
Phone: 617.697.6330 | E-Mail: msolarczyk@calsierra.com

Colin S. Stratford | Manager – Data Capture & Media Sales
Cal-Sierra Technologies, Inc.
39055 Hastings Street | Fremont, CA 94538
Office: 510.742.9996 | Mobile: 602.418.7934 | E-Mail: cstratford@calsierra.com

Step 4: Add a Tab command

To force the cursor to the next cell in SmartSheet, scan this “TAB” code:



ADD A TAB KEY

NOTE: This will force the cursor to move to the next cell to the right automatically in the SmartSheet.

Step 5: Testing and Validation

view | Dynamic Glass

WARNING: DO NOT REMOVE STICKER!
To be removed at final cleaning.
ADVERTENCIA: NO quite esta PEGATINA!
Quitada en la limpieza final.



LITE ID: 14154'0364'0071'0017'00
SIZE: 49" W x 116" H

THIS SIDE FACES INTERIOR

View, Inc. | 195 S. Milpitas Blvd., Milpitas, CA 95035 | (408) 263-9200
Patent Information - <http://www.view.com/patents>

view | Dynamic Glass

WARNING: DO NOT REMOVE STICKER!
To be removed at final cleaning.
ADVERTENCIA: NO quite esta PEGATINA!
Quitada en la limpieza final.



LITE ID: 14154'0364'0071'0017'00
SIZE: 49" W x 116" H

THIS SIDE FACES INTERIOR

View, Inc. | 195 S. Milpitas Blvd., Milpitas, CA 95035 | (408) 263-9200
Patent Information - <http://www.view.com/patents>

WARNING: DO NOT REMOVE STICKER! To be removed at final cleaning.
ADVERTENCIA: NO quite esta PEGATINA! Quitada en la limpieza final.

LITE ID:
14154'0364'0071'0017'00
SIZE:
49" W x 116" H



view | Dynamic Glass

THIS SIDE FACES INTERIOR
View, Inc. | 195 S. Milpitas Blvd., Milpitas, CA 95035 | (408) 263-9200
Patent Information - <http://www.view.com/patents>

Need Additional Help?

Contact your View Project Manager. Email LVEBootcamp@view.com or glaziertraining@view.com.